

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T

50X1-HUM

COUNTRY USSR (Leningrad Oblast)

REPORT

SUBJECT 1. Ship Construction in Leningrad Shipyards
2. Photograph of the Baltic and Krylov Shipyards

DATE DISTR. 4 April 1958

NO. PAGES 2

REFERENCES

50X1-HUM

DATE OF INFO.

PLACE & DATE ACQ.

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

Baltic Shipyard

50X1-HUM

1. The battleship way was apparently empty. On the cruiser way was a large hull on the stern of which a large deckhouse was being constructed. Work was also being done on the mid-section of the superstructure.
2. Four or five newly built motor launches lay at the fitting-out quay immediately east of the battleship way.
3. Three submarines, one [redacted] lay at the submarine fitting-out quay. Two of the submarines were moored side by side. One submarine had a step fore and aft on the conning tower. On the forward section of the conning tower were oval windows (ports) and an apparatus which resembled a plexiglass dome, as sketched below.

50X1-HUM

The submarine lying inside the one just described was considerably larger, and also had a step fore and aft on the conning tower as sketched below.

PROCESSING COPY

10 JUL 1958

S-E-C-R-E-T

50X1-HUM

STATE	X	ARMY	X	NAVY	##X	AIR	X	FBI		AEC									
(Note: Washington distribution indicated by "X"; Field distribution by "##".)																			

INFORMATION REPORT INFORMATION REPORT

50X1-HUM

S-E-C-R-E-T

-2-

Krylov Shipyard

4. A floating dock with an estimated capacity of 10,000 tons lay at the western end of the Krylov Shipyard. The way was hidden by this floating dock, but it was reported [redacted] that an atomic-power icebreaker was being completed on this way.

50X1-HUM

5. [redacted] showing the Baltic Shipyard at the left, the Krylov Shipyard at the right, and a submarine at the far left, taken [redacted]

50X1-HUM

50X1-HUM

Kanonerskiy Shipyard

6. Five old merchant ships undergoing repairs lay in Kanonerskiy Shipyard. Two of these ships, each about 5,000 DWT, were being modernized. A large merchant ship lay in the floating dock on the west side of the yard.

50X1-HUM

S-E-C-R-E-T


50X1-HUM

Sanitized Copy Approved for Release 2010/09/02 : CIA-RDP80T00246A041200530001-5

50X1-HUM

USSR Leningrad 59 55 N 30 15 E
BALTIC SHIPYARD AT LEFT, KRYLOV SHIPYARD (FORMERLY MARTI SHIPYARD) AT RIGHT.
SUBMARINE ~~PLANT~~ AT FAR LEFT.

50X1-HUM



Sanitized Copy Approved for Release 2010/09/02 : CIA-RDP80T00246A041200530001-5